



IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re Patent Application of:

Dae-Sung HAN et al.

Application No.: 10/652,492

Confirmation No.: 2700

Filed: September 2, 2003

U.S. Patent No.: 6,866,034 32

Issued: March 15, 2005

COOKING APPARATUS For:

ATTENTION

CERTIFICATE OF CORRECTION

BRANCH

Batch No.:

REQUEST FOR CERTIFICATE OF CORRECTION

Commissioner for Patents PO Box 1450 Alexandria, VA 22313-1450

Sir:

Patentees respectfully request that a Certificate of Correction be issued in the subject patent, pursuant to 35 USC § 254 and 37 CFR § 1.322, to correct the errors shown on the attached Form PTO-1050. A check in the amount of \$100 to cover the cost of the Certificate is attached.

One or more of the errors shown on the attached Form PTO-1050 is or are within the responsibility of the undersigned; each thereof is of a clerical or typographical nature or of minor character and occurred in good faith, and the correction thereof is consistent with the prosecution record.

11/28/2005 WABDELR1 00000069 6866034

01 FC:1811

100.00 DP

Respectfully submitted,

STAAS & HALSEY LLP

Date: 1011.25, 2005

Gene M. Garner, II

Registration No. 34,172

1201 New York Ave, N.W., Suite 700

Washington, D.C. 20005 Telephone: (202) 434-1500 Facsimile: (202) 434-1501

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO : 6,866,034 62

DATED: March 15, 2005

INVENTORS : Dae-Sung HAN et al.

It is certified that error appears in the above-identified patent and that said Letters Patent are hereby corrected as shown below:

Column 7

line 36 --plates-- should continue on same line with "reflecting";

Column 10

line 5, replace "part" with --port--.

MAILING ADDRESS OF SENDER: STAAS & HALSEY 1201 New York Avenue, N.W. Suite 700 Washington, DC 20005 PATENT NO. 6,866,034

No. of add'l copies @ 304 per page